GRATONCOMMUNITY SERVICES DISTRICT

250 ROSS LANE • MAIL: PO BOX 534, GRATON, CALIFORNIA 95444 • 707/823-1542



DATE: August 11th, 2022

TO: Members of the Board of Directors

FROM: John Gibson, Chief Plant Operator

SUBJECT: OPERATION REPORT, July 15th – August 11th 2022

Lift Station #1 Perimeter Fence

Coggins Fence & Supply has completed the fence extension at the Lift Station enclosing the PG&E panel and well.





Storage Shed Removal

The electrical box has been disconnected from the shed and the wiring tidied up in an underground Christy box. Pending a start date for the teardown and removal from Heauser Hauling.



GRATONCOMMUNITY SERVICES DISTRICT

250 ROSS LANE • MAIL: PO BOX 534, GRATON, CALIFORNIA 95444 • 707/823-1542



Regulatory Compliance

- Completed the Q2 2022 Electronic Self-Monitoring Report and Discharge Monitoring Report.
- CIWQS: July "No Spill Report" was completed.
- CIWQS: Submitted the ROWD.

Operations, Process Control, and Preventative Maintenance

Replaced the 4"X16' effluent pump pvc piping with a flexible hose and camlock fittings. This will
prevent future maintenance costs due to vibrations and water hammer on startup and shutdown
causing leaks and breaks at the glued connections.





- Pulled and de-ragged pond #1 aerators A and B.
- Continued irrigation on GCSD's irrigation fields, monitoring for runoff and breaks in the system.
- Repainted the elevation markings for the East and West holding ponds.
- Replaced the sump pump in the effluent monitoring well.
- Cleanup around the plant, removing garbage, debris, empty 55 gal. chemical drums and delivered to waste management for disposal.
- Replaced the settling pond wet well transducer.
- Continued daily rag removal and weekly shoveling of the grit chambers at the headworks. Draining rags and grit in perforated buckets and disposing in the hippo hopper.
- Drain and cleaned the turbidity meters, sensors, and housing weekly.
- Weed abatement around plant roadways.